

Mine Name: Bromide Basin

Inspector(s): Wayne Western

Surface Ownership: BLM/Fee

Operator Name: Bromide Mining LLC

Other Participants: John Reay (BLM)

Weather Condition: 60's clear skies

Bond Renewal Date: July 15, 2012

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program May 24, 2013

Reviewed:

Last Inspection: October 04, 2011

Bond Amount: \$25,000.00

Mineral Ownership: BLM/Fee

Permit Number: S/017/0031
Inspection Date: 05/21/2013
Time: 10:00 am – 10:50 am
Mine Status: ACT

Last Year of Production: 2012		Acreage: 5 acres		
	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer,			
2.	Bond/Bond Release			
3.	Annual Fees			
4.	Annual Report			
5.	Public Safety (shafts, adits, trash, signs, highwalls)			
6.	Protection of Drainages / Erosion Control			
7.	Deleterious Material			\boxtimes
8.	Roads (maintenance, surfacing, dust control, safety)			
9.	Concurrent Reclamation			
10.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
11.	Water Impoundments			
12.	Soils			
13.	Re-vegetation			
14.	Air Quality			

Purpose of Inspection:

15. Other

This was a routine inspection.

Inspection Summary:

The Permittee submitted an amendment to the NOI for expansion of the area. This was the result of a BLM finding that operations were being conducted outside of the permit boundaries. The Division requested that the Permittee provide detailed maps of the permit boundaries and the boundaries between BLM and fee ground.

The Division reviewed the bond and determined that a bond escalation was needed.

The permit fees were paid in 2013 and annual report submitted. Access to the site is restricted by a locked gate. Portals were closed.

Inspection Date: May 21, 2013

Page 2 of 4 S/017/0031

There is a large storage container that was damaged on the site an must be removed. There was also garbage on the site that must be cleaned up.

There is a waste oil drum on the site that is tipped over and leaking oil. There are buckets of hydraulic fluid that are leaking.

Some soils have been contaminated by the waste oil and hydraulic fluid and must be cleaned up.

Conclusions and Recommendations:

The bond needs to be increased.

The Division will issue a notice of violation for the oil spills.


Directions to Site:

Take the turn off for the Little Egypt geologic area.


Inspector's Signature

WHW:

cc: (OPERATOR)
John Reay, Hanksville BLM
Sue Fivecoat, Hanksville BLM
O:\M017-Garfield\S0170031-Bromidebasin\inspections\Insp-05212013.doc




Leaking bucker of hydraulic fluid. Notice contaminated soil.




Leaking bucket of waste oil. Notice oil stains on pipe and ground

Inspection Date: May 21, 2013 Page 4 of 4 S/017/0031



Bucket with contaminated soil.



Damaged shipping container.